

ATTORNEY'S DOCKET:  
004578.1147

PATENT NO:  
US 7,079,588 B1

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patentee: Paul E. Doucette et al.  
U.S. Patent No.: US 7,079,588 B1  
Issue Date: July 18, 2006  
Serial No.: 10/028,009  
Filing Date: December 21, 2001  
Confirmation No.: 2368  
Title: METHOD AND APPARATUS FOR PROCESSING SIGNALS IN  
AN ARRAY ANTENNA SYSTEM

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450


Dear Sir:

**REQUEST FOR CERTIFICATE OF CORRECTION**  
**UNDER 37 CFR § 1.322**

It is respectfully requested that a Certificate of Correction be issued in accordance with the enclosed Form PTO-1050. The error involved is believed to be a Patent Office error, and it is believed that no fee is due in association with this request for a Certificate of Correction. However, the Commissioner is hereby authorized to charge any fees or credit any overpayments to Deposit Account No. 02-0384 of Baker Botts L.L.P.

It is respectfully submitted that a significant error is present in the printed patent, that correction thereof in accordance with the enclosed Form PTO-1050 is required in order that no misunderstanding will occur.

Respectfully submitted,  
BAKER BOTTTS L.L.P.  
Attorneys for Applicants

  
Bradley P. Williams  
Reg. No. 40,227

Date: 5/30/08  
Customer No.: 45507  
Phone: (214) 953-6447

**UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION**

Patent No.: US 7,079,588 B1  
Dated: July 18, 2006  
Inventor(s): Paul E. Doucette et al.

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**Title Page:**

Page 2, Right Column, Line 5, after "GPS/" please delete "GLONASSS" and insert -- GLONASS --.

**Column 9, Line 16:**

After "phase shift" delete "01" and insert -- ø1--.

**Mailing Address of Sender:**  
Baker Botts L.L.P.  
2001 Ross Avenue, Suite 600  
Dallas, Texas 75201-2980

**Patent No.** US 7,079,588 B1